

ID	Type	Product	Feature	Name
48587	Other	Other	Adept 3.0	LN10.7 - Sync item cost script
49510	Other	Other	Adept 3.0	Page Load Slow - needs optimization
49540	Other	Other	Adept 3.0	ADEPT 3Prod - Performance Improvement Needed - Data on Header tab
49545	Other	Other	Adept 3.0	Performance - Project Search Page slow to load (3min)
49542	Other	Other	Adept 3.0	LogRocket reported issue for ADEPT3 [object Object] is not valid JSON
49421	BOM	Pumps	Adept 3.0	ADEPTLNTTEST for CRP2.0 - DEFAULTIRCPN for 4600 CS pump
48141	Other	DEVA	Capturing Footprint Savings & Installation Cost Savings for SG & FTV in DEVA	Changes to Piping Arrangements Window
48209	Other	Other	DCR-2021-010 DEPM 71	Error when selecting DE Strain Relief Parts
49530	Selection	Pumps	DCR-2022-001-Remove Obsoleted VIL Fire Pump Models	Obsolete DE models need to be corrected
49637	Selection	Pumps	DCR-2022-002 DE IVS 1-10hp NCP reduction	DCR-2022-002 Bug Fix 4 (3.7) kW motors still showing
49464	DCR	Fire	DCR-2022-003 HFHH Fire Pump 12x8x18NF	Configuration work for DCR-2022-003 HFHH Fire Pump 12x8x18NF
49465	DCR	Fire	DCR-2022-003 HFHH Fire Pump 12x8x18NF	New Engine work for DCR-2022-003 HFHH Fire Pump 12x8x18NF
49596	Other	Other	DCR-2022-013 Expansion Tank	DCR-2022-013 Expansion Tank - Dropdown not displayed under Sight Glass and Seismic clip tab
49607	Other	Other	DCR-2022-013 Expansion Tank	DCR-2022-013 - Expansion Product Item Weight is not matching with the Product catalogue
49547	DCR	Pumps	DCR-2022-015 Low cost VFD	COnfiguration work for DCR-2022-015 Low cost VFD
49182	Selection	Pumps	DCR-2022-015 Low cost VFD	Incident #69273 110kw and above IP ratings
49548	DCR	Pumps	DCR-2022-017 Medium Pump	Configuration work remainder before pilot DCR-2022-017 Medium Pump
49512	Other	Other	Engine QA Testing Tool	QA Test Tool Results are not matching with UI
49603	Other	Pumps	Engine QA Testing Tool	DE -QA Test Tool Results are not matches with UI
42660			Incident #33935 Adding new features and options (DEMC Test ring to read data from LN Data string instead of E-3212)	New Engine work for Incident #33935
49444	Selection	Pumps	New Engine :: Technical Debt [FOR LAUNCH]	Performance Improvement - VS Selection
49579	Selection	Pumps	New Engine :: Technical Debt [FOR LAUNCH]	LoadTesting Selection/Calculate Pump on Curve click:: System.OverflowException:
49580	Selection	Pumps	New Engine :: Technical Debt [FOR LAUNCH]	LoadTesting Selection/Calculate Pump on Curve :: Null Exception
49693	Other	Other	Pacdor Enhancements - 09 2022	#70459/#70516RE: Pacdor; Drawing unavailable 4300 1013-200.0
49694	Other	Other	Pacdor Enhancements - 09 2022	#71189Revit Standardization for IVS 101 DCR on DE Pumps
49695	Other	Other	Pacdor Enhancements - 09 2022	#71597 PacDOR Drawing Issue
49696	Other	Other	Pacdor Enhancements - 09 2022	#71962NCP reduction in India for 4300
49697	Other	Other	Pacdor Enhancements - 09 2022	#62351HSC Fire pump EAR00060 IEC Market
49698	Other	Other	Pacdor Enhancements - 09 2022	#73503Image not available for 42804x3x13L125Lb286JPODP
49699	Other	Other	Pacdor Enhancements - 09 2022	#72404RES: CAD File
49156	Selection	Fire	Post Launch - Catch All	Fire NFPA-Driver RPM modification from 2945 to 3000 and engine with same hp but double RPM to be removed
49276	Selection	Fire	Post Launch - Catch All	Fire unlisted ES pump construction update
49589	Selection	Fire	Post Launch - Catch All	NFPA Fire - Missing Pump in Search Result
49614	Other	Other	Post Launch - Catch All	Reported by Naveen-CS 4700 VMS 10:07B. Values should be calculated corresponding to Projected flow
49625	Other	Other	Post Launch - Catch All	CS 4280 150-315 pump - Grid Results is showing Blank for NPSHR Column
49569	Other	Pumps	Post Launch - Catch All	500 error-UK market for CS pump Manual selection
49407	Reports	Pumps	Post Launch - Catch All	Curve Update - Terminate Motor lines at EoC (DEPM Pumps)
49591	Reports	Pumps	Post Launch - Catch All	FullCapabilityHead and FullCapabilityEff values being overwritten
48986	Selection	Pumps	Post Launch - Catch All	Need Compliant Check for Manually selected Pumps
49428	Selection	Pumps	Post Launch - Catch All	Review NPSHR Curves - 4300 0408-010.0
49479	Selection	Pumps	Post Launch - Catch All	DE Corner points to be corrected in NE
45172	Selection	Pumps	Post Launch - Catch All	Incident #45397 RE: [Malaysia/Ultime] SQJMA000018_1 - Kwasa Project
49538	Selection	Pumps	Post Launch - Catch All	VMS 2:2 0.37kW VMS not showing in search results
49544	Selection	Pumps	Post Launch - Catch All	4030 100-200 30kW CS missing from search
49597	Selection	Pumps	Post Launch - Catch All	4030 100-330H 4p 30kW not showing in Search Results
49174	Other	Other	Pricing Service	Residential Pumps (Circulators) - Part Number Column is missing for 1050 and 1060 models.
49177	Other	Other	Pricing Service	Residential Pumps (Circulators) - Part Number Column is blank for H ECM and S ECM models.
49176	Other	Pumps	Pricing Service	AGE3 for ME And UK Missing Part Number Column
49163	Pricing	Pumps	Pricing Service	Add Circs Prices from Excel Files to SQL queries
49272	Pricing	Pumps	Pricing Service	Load Pump Prices from CPQ Matrices
49453	Other	Other	Pricing Update - July 2022	Replacement Listed Bareshaft FP grid price mismatches
49454	Other	Other	Pricing Update - July 2022	OEM Listed Bareshaft Fire pump Grid price mismatch
49491	Other	Other	Pricing Update - July 2022	VS - US_LA Market - Grid price mismatches
49106	Other	Other	Pricing update May 2022	CA Market Replacement Jockey Pump Controller - Quote Price Mismatch
49590	Selection	Boosters	Pump Search - Boosters Search Phase 1	Booster Engine - I221802 incorrect in ADEPT

ID	Type	Product	Feature	Name
44925	Selection	Fire	Pump Search - LPC Fire [PHASE 2 LAUNCH]	LPC Search Results Tables
46815	Other	LPC	Pump Search - LPC Fire [PHASE 2 LAUNCH]	LPC Case 7 System Selection Process
46816	Other	LPC	Pump Search - LPC Fire [PHASE 2 LAUNCH]	LPC Case 8 System Selection Process
46817	Other	LPC	Pump Search - LPC Fire [PHASE 2 LAUNCH]	LPC Case 9 System Selection Process
47881	Selection	LPC	Pump Search - LPC Fire [PHASE 2 LAUNCH]	LPC Curve Service :: Show Curve for Case 1, 2 and 3
48197	Selection	LPC	Pump Search - LPC Fire [PHASE 2 LAUNCH]	UAT - JSON Out Values incorrect - LPC
48749	Selection	LPC	Pump Search - LPC Fire [PHASE 2 LAUNCH]	UAT - NPSHr Value too high - LPC
48876	Selection	LPC	Pump Search - LPC Fire [PHASE 2 LAUNCH]	UAT - Case 12 - Incorrect Pump Data on Selection Information Page - LPC
49360	Other	Other	Pump Search - LPC Fire [PHASE 2 LAUNCH]	LPC submittal report - Power Curve Issue - Power Curve is not extended till end point
47118	Drawing	Boosters		Incident #52550 - Performance Curves
49392	Reports	Boosters		Incident #71092 FW: Booster being shipped without headers, issues with dimensions , SQ0054535
48771	Selection	Boosters		Incident #64439 Tank Removal Notification For Booster Post Select
49447	Reports	Expansion		Incident #71998 AET Expansion Tanks
45129	BOM	Fire		Extract NFPA Fire Diesel BOM data for engineering
49062	BOM	Fire		Reg Test 79 - NFPA Fire - Default Partnumber
47231	Drawing	Fire		Line Drawing Missing - Incident #47703 FW: URGENT URGENT
49197	Drawing	Fire		Incident #69673 missing drawings
49513	Reports	Fire		Incident #72194 Adept Quote; Specification report error
47413	Selection	Fire		Incident #53652 Adept - VIL replacement not available
49605	Selection	Fire		Cannot assign value of 125.1 of Datatype Number into String
49520	Shipment Indicator	Fire		Reg test 83 - Replacement Firetrol controller lead time
49523	Weights	Fire		To remove the duplicate Values from matrix (HSCDieselFirePumpDwgDims)
49413	Reports	FTV		Incident #71302 Submittal not generating for FTVs if selected specifically
48844	Selection	FTV		Incident #65215 FTV Bug - Pump flange rating = ANSI -125 (default) for Pipe type (Flanged)
49181	Reports	LPC		Incident #36781 LPC Adept - Motor Manufacturer shown on quote report/submittal curve
49613	Reports	LPC		LPC orifice and peak power - JP review
49015	BOM	OEM		Incident #66914 Daikin BOM Configurator Update - 4x4x8 & 5x5x13 E coated casings - EAR#100456
44982	Selection	OEM		Incident #46150 Adept JCI pump error
49056	BOM	Other		BaaN Placeholder for June release
49071	Other	Other		Control Data missing from submittal for compass - configuration
49469	Other	Other		BaaN Placeholder
49471	Other	Other		Default Part number Placeholder
49532	Other	Other		determine obsolete pricing matrices
49572	Other	Other		10.5 to 10.7 rule comparison and fix
48411	Other	Other		India - ES fire pumps - Drawings missing
49511	Other	Other		Blocked by 49660-Reported by Naveen-Incorrect Max frequency
49556	Other	Other		LPC Curve issues from JP testing
49615	Other	Other		Reported by Maggie-Outdoor iFMS Controls Enclosure
49616	Other	Other		Reported by Maggie - IPS error when Plant Configuration is changed
49617	Other	Other		Reported by Maggie - Export shipping 5% adder not added to existing (IPS,IPC,Pumps,FTV,SG)
49644	Other	Other		Incident #74419 FW: Hydronic System Replacement - Guelph Armoury - 7 Wyndham St S
49660	Other	Other		Incorrect Envelope area for pump 4300 0815-050.0 - NewEngineTest
49688	Other	Other		4270 selections are broken via Manual Selection
49611	Shipment Indicator	Other		Shipment indicator Update for LA Market
48294	BOM	Pumps		4600 125-240M Pump size Configuration BOM to be added in CPQ and Interchart for IEC Markets
48739	BOM	Pumps		Incident #64572 Outdoor DEPM - Small Gen 5 - Frames 90, 90s and 112
48911	BOM	Pumps		HVAC IEC 4600 PUMPS with DefaultPN for Coupling/Baseframe and missing from Interchart
46618	BOM	Pumps		Regression Test - CVS 4300 3000rpm 450hp Motor Partnumber missing
47896	BOM	Pumps		4380 and 4372 BOM Text to be removed as marked up by Rami
48595	BOM	Pumps		Reg Test 76 - Default Partnumber for Pumps APR market
49067	BOM	Pumps		Reg Test 79 - Commercial pumps - Default Partnumber
44065	Other	Pumps		Incident #34657 - Astromulti speed with TA option reverts to original part number when validation occurs.
46540	Other	Pumps		Incident #49555 SAA-10A
49550	Other	Pumps		End of curve issue with 4270 pump sizes
45299	Reports	Pumps		Incident #47755 FW: Pump motor & controls protection - Specification
46930	Reports	Pumps		Incident #43417 FW: 2018-641 SM68 Additional Pumps for Snow Melt.pdf

ID	Type	Product	Feature	Name
44907	Selection	Pumps		Incident #45780 FW: 6 series circs - the shaft material shown in ADEPT is not 416 stainless steel
46989	Selection	Pumps		Incident #47182 - SQGVI002193-1 - Unable to select customer choice motor
48772	Selection	Pumps		Incident #64787 RE: 20A063873 - SRS Enterprises - SINGLE PHASE cannot have SGR's
49576	Selection	Pumps		Incident #73659 RE: 10x10x13 / 10x8x13 impeller
45108	Selection	Pumps		Incident 46952 - FW: Ram's items - All Bronze Construction Issue
48896	Selection	Pumps		Incident #65983 Discrepancy 60 hz pump selection
49016	Selection	Pumps		Incident #67020 SQJQI000271-1
49350	Selection	Pumps		incident #41681 defaultpn not correcting after Change Options
49555	Selection	Pumps		Incident #73301 RE: 10A040087
49557	Selection	Pumps		Reg Test 84 - Getresults button visible even for blank fields via Pumps Manual select
49562	BOM	Service		Baan: B#73342,B#73426,
49604	BOM	Service		Baan : B#73108,B#73479,B#73602,B#73809
49624	BOM	Service		Baan:B#74042,B#74091,B#74084,B#73077,B#74165,B#74190,B#74232
48759	BOM	Service		Reg Test 77 - Default partnumber servicekits-Seal and blanking kit
48315	Reports	Service		Incident #61072 SMART Services Verbiage Quotation Update
49518	BOM	Shell and Tube		Reg test 83 - Shell n Tube default partnumber
48579	Drawing	Shell and Tube		Incident #42703 - RTB drawings not showing correct Head Type
48600	Reports	Shell and Tube		Incident #62254 Heat Transfer Coeff. value seems incorrect (for customer : Spirax Sarco [SQ0045621-1])
46992	Selection	Shell and Tube		Incident #48826 - 500 Error being Generated for WS S&TH HX w/ F Type Construction
47628	Selection	Startup And Commissioning		Incident #55623 [Region price bug] The region for standard startup and commissioning is missing resulting in \$0
49578	Weights	VAS		Incident #73383 Vortex Air Separator Weight is in KG but showing in LB when added using configurator
49610	Selection	VFD		Missing VFD Part Number in BOM Data section
28504				INDIA and US-Grid Price not matched with Price sheet